

Division of Oil, Gas, & Mining
Mining Report

04/05/95

MINE ID: M0450017

MINE NAME: MERCUR MINE

OPERATOR: BARRICK MERCUR GOLD MINES, INC
CONTACT: DAVID P. BEATTY
ADDRESS: P O BOX 838
TOOELE UT 84074

PHONE: (801)268-4447

Surface Owner: PRIVATE
Mineral Owner: PRIVATE

BLM #:
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
		PR				4	6.0S	3.0W
						8	6.0S	3.0W
						32	5.0S	3.0W

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: ACT

Acreage: 905

Status Date: / /

Minerals Mined
AU, AG

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

03/10/81

05/01/81

10/13/81

07/13/93

BOND TYPE: SELF BOND

BOND AMOUNT: \$\$8,808,891

ANNUAL REPORT YEAR: 94

	YTD	Total	DATE ISSUED:	DATE RESOLVED:
NONCOMP NOTICES:	0	0	/ /	/ /
VIOLATIONS:	0	0	/ /	/ /
REVISIONS:	0	0	/ /	/ /
AMENDMENTS:	0	1	03/11/92	05/18/92

COMMENTS:

INSPECTION MADE TO EVALUATE AREAS RECENTLY RECLAIMED & TO PROPOSE RECLAMATION TECHNIQUES FOR DIFFICULT AREAS. BARRICK ATTEMPTED TO CAST TOPSOIL ONTO SNIDER DUMP, BUT WAS NOT SUCCESSFUL. DUMP TOO STEEP & SOIL SLID TO BOTTOM OF DUMP. TOP & UPPER PORTION OF THE SLOPES HAVE FORMED A DURABLE CRUST DUE TO THE CLAY CONTENT OF THE DUMP MATERIAL. CANNOT REGRADE THE DUMP TO A 2:1 BECAUSE IT MAY PLACE MATERIAL ON THE MAIN ACCESS ROAD BELOW. NORTH MERCUR DUMP IS AT ANGLE OF REPOSE & HOLDING HYDROMULCH MIX QUITE WELL. SNIDER DUMP NEEDS MORE INSPECTION.